

Celectricity

Bringing energy to your door

書畫書

Tap Changer

Acoustic/Vibration-Based Condition Monitoring System

Stay connected... Stay connected... f in in www.enwl.co.uk

Background

NIA funded project to test feasibility of detecting problems

Acoustic/ vibration acquisition system Record information during each tap change switching event for a period of two years

Goal: to process recorded data with DSP and AI tools looking for trends referable to ageing of tapchanger

Will lead to improved asset management of tap changers



System overview







Mains power input

Acquisition module





High and not scalable cost

Relatively low sampling frequency (50kHz)

Proprietary and high cost development tools (LabView)

Limited amount of data means high failure risk of statistical analysis approach



Acquisition model





Complete custom USB acquisition module designed

Flexible 8 channel 24bit 192kHz differential input

Auxiliary isolated analogue input

Auxiliary isolated digital I/O

4 input for RTD temperature sensor

USB interface compatible with any Linux PC using standard drivers

Acquisition module designed and tested in about 6 months

Cost effective and quantity scalable solution

5

Vibration and acoustic sensors



Analysis of mechanical vibration produced by gear and switch

Require sensor capable of vibration detection with phase coherence across spectrum up to 10kHz

ICP Industrial accelerometer used (0.5 to 10-15kHz)





Vibration and acoustic sensors



Detection of noise produced by arcing and PD during switching

Require sensor capable of detect high frequency acoustic energy (> 50kHz, where mechanical noise roll off)

Acoustic emission resonating sensor used (15 to 150kHz)





Vibration and acoustic sensors

Acquisition module can sample up to 192kHz so can be used with all kind of sensor (AE requires specific preamp)

Hi quality industrial accelerometer is similar cost to AE sensor and seems capable to detect energy up to 100kHz.





Electro-mechanical system



in the

Buzby2 EPC

Acquisition Module

GSM Antenna

0





Cooling and Heating system

Power Supply

Customized enclosures suitable for indoor/outdoor

Project status





Alpha Prototype Installations





3 Alpha prototype installed and commissioned on July 2017 Winifred Road Primary Altrincham Grid Baguley Primary Complete waveform from Accelerometer and CTs @ 192kHz Temperatures Tap position for each switching event All data sent to remote server

Introduction of specific lossless compression reduced data size by 50% Installed system generate on average 3/4 events per day each around 15/25MB

Each system should generate about 2/3 GB per month Down sampling of CT's waveform should be implemented to reduce data of about 30%

Preliminary "handcrafted" data analysis has identified issues on 2 of 3 monitored tap changers



Alpha prototype installation: Winifred Rd

Site: Winifred Road Primary

Tap changer type: Ferranti DC3

During the selector movement phase of last step of switching sequence 5->4->3 or 3->4->5 arcing noise presence can be clearly heard.



Event_ID	BS_TapPos[#]	AS_TapPos[#]	
20170717T052222	3		4
20170717T055305	4		5
20170717T055808	5		4
20170717T080014	4		5
20170717T081220	5		4
20170717T091245	4		3
20170717T091806	3		4
20170717T162033	4		3
20170717T163919	3		4
20170717T172635	4		5
20170717T173504	5		4
20170717T191248	4		3
20170717T192946	3		4
20170717T193015	4		5
20170717T194042	5		4
20170717T204802	4		5
20170717T213717	5		4
20170717T234952	4		3





Alpha prototype installation: Winifred Rd



The arcing noise indicates that tap 4 contact of one of the three selectors is excessively worn



Observing tap usage statistics shows that tap 4 is the most used tap position. **Currently the tap changer is on fixed tap awaiting inspection.**



Alpha prototype installation: Altrincham

BS TapPos[#]

8

8

9

8

9

8

8

9

8

7

8

8

9

AS TapPos[#]

8

8

9

8

9

8

8

9

10

7

8

8

9

8



Site: Altrincham Grid

Tap changer type: **Fuller HS319** ● Recorded anomalous events ● 2/3 time per week always involving tap 8 ● Currently under investigation

anomalous events • 2/3 ently under investigation	

20170812T065819	12/08/2017 06:58	5	10	9	
20170812T081414	12/08/2017 08:14	5	9	8	
20170813T004753	13/08/2017 00:47	3	8	8	
20170813T005010	13/08/2017 00:50	3	8	8	
20170813T005236	13/08/2017 00:52	5	8	9	
20170813T065700	13/08/2017 06:56	5	9	10	
20170813T081430	13/08/2017 08:14	5	10	9	

Event_Time[s]

3

5

5

5

5

3

5

5

6

6

3

5

6

Event ID

20170726T140949

20170726T231255

20170726T231433

20170727T061730

20170728T234721

20170729T063347

20170729T101106

20170730T014838

20170730T043726

20170802T153206

20170802T210651

20170802T232039

20170802T232254

20170803T055703

BS Timestamp

26/07/2017 14:09

26/07/2017 23:12

26/07/2017 23:14

27/07/2017 06:17

28/07/2017 23:47

29/07/2017 06:33

29/07/2017 10:11

30/07/2017 01:48

30/07/2017 04:37

02/08/2017 15:32

02/08/2017 21:06

02/08/2017 23:20

02/08/2017 23:22

03/08/2017 05:56