



Code of Practice

306

Section 9

Fitting Tasks

Issue 7 August 2026

Amendment Summary

Issue No/Date	Description
Issue 1 August 2021	Complete reformatting of CP306. All procedures within this section have been given an issue number as they never had one before. Prepared by: Matthew Kayes Approved by: Policy Approval Panel and signed on its behalf by Steve Cox, Engineering and Technical Director
Issue 2 April 2022	Section 9 colouring updated. Minor formatting changes to CRMS to NMS as marked in all Section 9 FM1 to 3. Part 10 of FM9_001 updated to clarify cables across doorways. Control measures updated in all documents. Prepared by: Policy Approval Panel Approved by: Technical Policy Panel and signed on its behalf by Paul Turner, PAP Chair
Issue 3 May 2022	FM9_001 has been updated to cover cable runs in walkways in close proximity to Open LV Boards and section footers updated in the other documents FM1 to 3. Prepared by: Matthew Kayes Approved by: Policy Approval Panel and signed on its behalf by Steve Cox, DSO Director
Issue 4 June 2022	New Section 9 FM 004 added for reflex units. Prepared by: Simon Rushton. Authorised by: Policy Approval Panel and signed on its behalf by Steve Cox, DSO Director
Issue 5 December 2023	Section 9 FM_004 amended to include guidance on Lucy FRMU and VRN/VRN2 ring main units. Prepared by: Simon Rushton. Authorised by: Policy Approval Panel and signed on its behalf by Paul Turner, PAP Chairperson
Issue 6 January 2026	Section 9 FM_003 amended to include guidance on NX44 EFI's. New Section 9.2 added for three CT's on triplex cable. Section 12 Updated to include the new cable needed for 3 CTs.

	New Section 14 added for the NX44 and all subsequent sections re-numbered. Section 15 updated to add NX44 image. Section 9 FM_004 updated to include R3/R4, J3/J4 and IB4 units. New Section 9 FM_005 added for installation of HX10 units. Prepared by: Matthew Kayes and Adnan Ali Authorised by: Policy Approval Panel and signed on its behalf by Paul Turner, PAP Chairperson
Issue 7 August 2026	Section 9 FM_004 amended to include new clamp to stop the selector moving due to vibration and also new shims added for the drive rid clamp in Section 25 – AEI IB4 and new operating arm brackets in Section 26 – J3/J4. Prepared by: Adnan Ali. Authorised by: Policy Approval Panel and signed on its behalf by Paul Turner, PAP Chairperson

NOTE: This Amendment Summary records amendments to the individual document(s) within this section of the Operations Manual.

Contents

Index of Section 9

5

All Rights Reserved

The copyright of this document, which contains information of a proprietary nature, is vested in Electricity North West Limited. The contents of this document may not be used for purposes other than that for which it has been supplied and may not be reproduced, either wholly or in part, in any way whatsoever. It may not be used by, or its contents divulged to, any other person whatsoever without the prior written permission of Electricity North West Limited.

Index of Section 9

Procedure	Issue number	Issue date	Description
FM9_001	3	May 2022	Installation of Ground Mounted RTU's
FM9_002	3	May 2022	Commissioning of Ground Mounted RTU's
FM9_003	4	Jan 2026	Installation of Earth Fault Indicator (EFI) Units
FM9_004	4	July 2026	Installation of RX10 Units
FM9_005	1	Jan 2026	Installation of HX10 units